





















Site Information	Depth (in)	Aliquot 1		Aliquot 2		Aliquot 3		Aliquot 4		Aliquot 5		
Site: 35 th Avenue Superfund Site Contract: EP-S4-15-01 TDD: 0002/OT-02-002 OSCs: Rick Jardine Property ID: CV0401B Date: January 15, 2015 Times: 6” 10:30 12” -- 18” -- 24” -- Photographer: Jerome Partap Official Photograph Set No.: 1 Hang auger soil description by interval and related pictures for sample location CV0401B.	0	Grass, brown sandy silt w/ coal fragments and gravel, bricks, damp, no odor.		Grass, black sandy silt w/ coal fragments and gravel, bricks, damp, no odor.		Grass, black sandy silt w/ coal fragments and gravel, bricks, damp, no odor.		Grass, black sandy silt w/ coal fragments and gravel, bricks, damp, no odor.		Grass, brown sandy silt w/ coal fragments and gravel, bricks, no odor.		
	6									Refusal at 6”		
		Refusal at 7”		Refusal at 8”		Refusal at 9”		Refusal at 8”		Refusal at 6”		
	12											
		Refusal at 7”		Refusal at 8”		Refusal at 9”		Refusal at 8”		Refusal at 6”		
	18											
		Refusal at 7”		Refusal at 8”		Refusal at 9”		Refusal at 8”		Refusal at 6”		
	24											